



Safety Alert: Dingli Australia - Product Safety Bulletin

Date: 23rd February, 2016

The EWPA has been notified by Dingli Australia of a potential stability related issue with their range of Slab Style scissor lifts manufactured before 2014.

Dingli Australia advise that a retrofit solution is being developed that will be applied to affected scissor lift models. Dingli Australia will issue a notice requesting owners to register with them so that arrangements can be made to have a kit fitted.

Dingli Australia have advised that until the retrofit has been carried out, affected machines should only be operated indoors (i.e. not exposed to wind) and the number of occupants in the platform limited to one person.

Owners of Dingli slab style scissor lifts are advised to contact Dingli Australia for further information.

Contact Details: serviceparts@dingliaustralia.com.au,
ph: 1300 623 622 or 07 3804 3334,
fax: 07 3804 3332,
www.dingliaustralia.com.au