

ABN: 581 0133 2165

LG TRAVEL TOWER SERVICES PTY LTD.

Phone: 03 97064378 Fax: 03 97064375

Field bulletin FB 0001 “

30-11-2020.

Our records show that you are the owner of an LGTTS Elevating Work Platform

Model number: GP14-300

Serial Number: 0007

We have become aware of an incident involving an LG model GP14 that occurred in Western Australia last week. We have no information other than a press report which appears to indicate catastrophic failure on the lower boom insert in the vicinity of the lower boom cylinder connection. Our records indicate that this unit was 9 ½ years old.

As a precaution we request you conduct the following structural inspections:



1. At the end the lower boom insert on the top, the sides and underneath for any sign of cracking or movement or corrosion
2. On the interior for signs of corrosion and cracking.
3. Check for looseness in the insert by watching the boom during raising, lowering and slewing movements – placing the basket on its rest and then raise the boom.

These inspections should be completed at your earliest convenience. We would be happy to conduct these inspections for you if required.

For our records:

PLEASE COMPLETE THE FOLLOWING AND REPLY TO THIS EMAIL

1. COMPANY
2. NAME
3. Phone Number

I confirm I have inspected the LGTTS MEWP,

Model number: Serial Number:

according to the procedure above.

(Please advise any observations here, include photographs if necessary)

IF YOU HAVE ANY CONCERNS REGARDING THIS INSTRUCTION PLEASE CONTACT
LGTTS .

If you have disposed of your unit, please advise LG Travel Towers and provide the contact details of the new owner (if known).