



Safety Alert: Dingli Australia - Product Safety Bulletin

Date: 6 July, 2017

Dear EWPA Member,

Following the Safety Alert: "Dingli Australia - Product Safety Bulletin Date: 23rd February 2016," the EWPA is assisting Dingli to locate the last 20 machines that require a retrofit solution.

If you own, have owned, sold or know the whereabouts the following machines, please could you contact Dingli Australia.

Contact Details: serviceparts@dingliaustralia.com.au,
ph: 1300 623 622 or 07 3804 3334,
fax: 07 3804 3332,
www.dingliaustralia.com.au

The machine details are as follows:-

MODEL	SERIAL NUMBER
S0608EH	MA100222-10
S06-E	AU101008-26
S06-E	MA100801-10
S1012E	AU120209-1
S06-E	AU120503-1
S06-E	AU101008-17
S06-E	AU101008-24
S06-E	AU101008-27
S06-E	AU101008-28
S06-E	AU101008-33
S06-E	AU101008-53
S06-E	AU101008-60
S0608EH	AU110510-29
S0808EH	AU111026-1
S0808EH	AU111026-2
S06-E	AU120808-2
S06-E	AU120808-3
S0608EH	MA100222-1
S0608EH	MA100222-3
S1012E	AU130227-3